Calibrate Touch Screen

1. Open "My device"



2. Open "control panel"

<u>File E</u> dit <u>V</u> iew <u>G</u> o	N? ×
3 🗣 🛊 🎓 🗙 🖸 📰 🖷	
Name	S
C Application Data	
My Documents	
NandFlash	
😴 Network	
🗁 Program Files	
🗁 Temp	
C Windows	
🔐 Control Panel.Ink	23 byt
PCPkInst.log	3.20
<	>

Η I • T Λ R G E T

3. Open "stylus"



4. Choose "calibration"

Stylus Properties ? OK 🔀	
Double-Tap Calibration	
If your device isn't responding properly to your taps, you may need to recalibrate your screen.	
To start the rec Click here s, tap	
Recalibrate	

HI T Λ R G E T

5. You will get the figure below. Follow the cross-shaped flag to complete the calibration.



6. After finish the calibration and get the figure below, press the button "Ent"(this is very important)

ew calibration settings have been measured ess the Enter key to accept the new setting Press the Esc key to keep the old settings.